

Rolls Royce RB211-535E4

ANNULUS FILLER



Reference

Engine Manual 72-31-11

Typical Part Numbers

UL16208, UL35848, UL35853, UL38852, UL38855, FW61408

General Information

22 Fillers per Engine

Aircraft Type: B757

Available Repair Scope

Basic Overhaul:

Engine Manual Inspections

| | |
|----------|---|
| FRS 3002 | Repair 1 - Replace Wire Thread Inserts |
| FRS 3253 | Repair 1 - Blend Minor Damage |
| FRS 5135 | Repair 1 - Replace Air Sealing Strips and Buffer Pads |
| FRS 1520 | Repair 2 – Apply White Epoxy Paint |
| FRS 1521 | Repair 3 - Reapply Dry Film Lubricant |
| FRS 5742 | Repair 32 – Anodizing Coating |

Service Bulletins:

| | |
|------------|-------------------------|
| SB 72-C545 | Eddy Current Inspection |
| SB 72-F194 | Ultrasonic Inspection |

1150 West Bradley, El Cajon, CA 92020

Phone: (619) 258-5109

E-mail: Repairs@USA.GKNAerospace.com

www.GKNAerospace.com

