



IAE V2500 ANNULUS FILLER

Reference

Engine Manual 72-31-11

Typical Part Numbers

5A0353, 5A1459, 5A1611, 5A1638, 5A1710, 5A1750, 5A1752, 5A1753, 5A6533

General Information

22 Fillers per Engine

Aircraft Type: A319, A320-200, A321-100/-200, MD90-10/-30/-40

Available Repair Scope

Engine Manual Inspection/Check 1

Repair 1/28 VRS 1004/1014 - Surface Damage Repair

Repair 2/27 VRS1009/1016 - Heat Resistant ES Coating Replacement

Repair 3/22 VRS 1007/1018 - Seals & Bumper Pad Replacement

Repair 4/20 VRS1008/1735 - Dry Film Lubricant Replacement

Repair 5 VRS1010 - Locating Pin Replacement

Repair 14/23 VRS1013/1017 - Helicoil Insert Replacement

Repair 19 VRS 1019 - Anodized Coating Replacement

SB 72-0234 Trim Platform Edge

SB72-0356 Ultrasonic Inspect Front Trunion

GKN Aerospace Repair Solutions West
1150 West Bradley Avenue
El Cajon, CA 92020
Visit us at: www.gknaerospace.com/fan-blade-repair