



## RB211-535 E4 1st Stage ANNULUS FILLER

### Reference

Engine Manual 72-31-11

### Typical Part Numbers

UL16208, UL35848, UL35853, UL38852, UL38855, FW61408

### General Information

22 Fillers per Engine

Aircraft Type: B757

### Available Repair Scope

#### Basic Overhaul:

Engine Manual Inspections

FRS 3002	Repair 1 - Replace Wire Thread Inserts
FRS 3253	Repair 1 - Blend Minor Damage
FRS 5135	Repair 1 - Replace Air Sealing Strips and Buffer Pads
FRS 1520	Repair 2 – Apply White Epoxy Paint
FRS 1521	Repair 3 - Reapply Dry Film Lubricant
FRS 5742	Repair 32 – Anodizing Coating

#### Service Bulletins:

SB 72-C545	Eddy Current Inspection
SB 72-F194	Ultrasonic Inspection

GKN Aerospace Repair Solutions West  
1150 West Bradley Avenue  
El Cajon, CA 92020  
Visit us at: [www.gknaerospace.com/fan-blade-repair](http://www.gknaerospace.com/fan-blade-repair)