


# Rolls Royce RB211-535E4 STAGE 1 FAN DISC



## Reference

Engine Manual 72-31-12

## Typical Part Numbers

UL16174, UL16175, UL16194, UL21343, UL24536

## General Information

Aircraft Type: B757

## Available Repair Scope

### Basic Overhaul:

Engine Manual Inspections

FRS 3253	Blend Minor Damage
FRS 3410	Blend Curvic Teeth
FRS 4965	Blend Minor Scores
FRS 4966	Blend Minor Nicks
FRS 5083	Replace Anti-Score Ring
FRS 5640	Remove Fretting from Bucket Groove
FRS 5669	Replace Dry Film Lubricant and Chocking Pads
FRS 5673	Shot Peen Disc

### Service Bulletins:

SB 72-8354 Install New Chocking Pads

1150 West Bradley, El Cajon, CA 92020

Phone: (619) 258-5109

E-mail: [Repairs@USA.GKNAerospace.com](mailto:Repairs@USA.GKNAerospace.com)

[www.GKNAerospace.com](http://www.GKNAerospace.com)

