

# Rolls Royce Trent 800 ANNULUS FILLER



## Reference

Engine Manual 72-31-11

## Typical Part Numbers

FK21221 / FW32707

## General Information

26 Fillers per Engine

Aircraft Type: B777

## Available Repair Scope

### Basic Overhaul:

Engine Manual Inspections

FRS 3253 Blend Minor Damage

FRS A056 Repair 12 - Replace Air Sealing Strips and Buffer Pads

FRS A043 Repair 2 – Local Anodize as required and Apply Surface Protection, White Epoxy Paint

FRS A046 Repair 3 - Reapply Dry Film Lubricant

1150 West Bradley, El Cajon, CA 92020

Phone: (619) 258-5109

E-mail: [Repairs@USA.GKNAerospace.com](mailto:Repairs@USA.GKNAerospace.com)

[www.GKNAerospace.com](http://www.GKNAerospace.com)

*Proprietary Information - Revised 12-21-2013*

