

Rolls Royce Trent 800

SLIDER PLATE



Reference

Engine Manual 72-31-11

Typical Part Numbers

FK22216, FW12655, FW13925

General Information

26 Fillers per Engine

Aircraft Type: B777

Available Repair Scope

Basic Overhaul:

Engine Manual Inspections

FRS A049 Repair 2 - Replace Dry Film Lubricant

FRS A015 Repair 15 – Replace Chocking Spring

Service Bulletins:

SB 72-C905 Part Number Modification



1150 West Bradley, El Cajon, CA 92020

Phone: (619) 258-5109

E-mail: Repairs@USA.GKNAerospace.com

www.GKNAerospace.com