

IAE V2500 ANNULUS FILLER



1150 West Bradley, El Cajon, CA 92020

Phone: (619) 258-5109

E-mail: Repairs@USA.GKNAerospace.com

www.GKNAerospace.com

Reference

Engine Manual 72-31-11

Typical Part Numbers

5A0353, 5A1459, 5A1611, 5A1638, 5A1710, 5A1750,
5A1752, 5A1753, 5A6533

General Information

22 Fillers per Engine

Aircraft Type: A319, A320-200, A321-100/-200, MD90-10/-30/-40

Available Repair Scope

Engine Manual Inspection/Check 1

Repair 1/28	VRS 1004/1014 - Surface Damage Repair
Repair 2/27	VRS1009/1016 - Heat Resistant ES Coating Replacement
Repair 3/22	VRS 1007/1018 - Seals & Bumper Pad Replacement
Repair 4/20	VRS1008/1735 - Dry Film Lubricant Replacement
Repair 5	VRS1010 - Locating Pin Replacement
Repair 14/23	VRS1013/1017 - Helicoil Insert Replacement
Repair 19	VRS 1019 - Anodized Coating Replacement
SB 72-0234	Trim Platform Edge
SB72-0356	Ultrasonic Inspect Front Trunion

