

# CFMI CFM56-7B FAN BLADE PLATFORM

## Reference

Engine Manual Section 72-21-20

## Typical Part Numbers

340-001-814-0, 340-001-816-0 and 340-001-817-0

## General Information

24 Platforms per Engine

Aircraft Type : B737-600, -700, -800, -900



## Available Repair Scopes

Engine Manual

Repair -002

Repair -003

Repair -006

Repair -007

Repair -008

Repair -009

Service Bulletin 72-0586

Inspection / Check -001

Replacement & Bonding of Elastomer Seals

Reconditioning of Protective Coating

Weight Adjustment

Repair the Forward End Concave Side

Blend Corrosion

Forward Lug Blending (Configuration 1 only, 340-001-814-0 & 340-001-816-0)

Replace Elastomer Seal & re-identify from -814 to -816

GKN Engine Systems Component Repair Sdn Bhd

No. 1, 3 & 5, Jalan Teknologi Perintis 1

Taman Teknologi Nusajaya

79250 Iskandar Puteri, Johor Darul Takzim, Malaysia

E-mail: Repairs@USA.GKNAerospace.com