



# Rolls Royce Trent 800 ANNULUS FILLER

## Reference

Engine Manual 72-31-11

## Typical Part Numbers

FK21221 / FW32707

## General Information

26 Fillers per Engine

Aircraft Type: B777

## Available Repair Scope

### Basic Overhaul:

Engine Manual Inspections

FRS 3253 Blend Minor Damage

FRS A056 Repair 12 - Replace Air Sealing Strips and Buffer Pads

FRS A043 Repair 2 – Local Anodize as required and Apply Surface Protection,  
White Epoxy Paint

FRS A046 Repair 3 - Reapply Dry Film Lubricant

GKN Aerospace Repair Solutions West  
1150 West Bradley Avenue  
El Cajon, CA 92020  
Visit us at: [www.gknaerospace.com/fan-blade-repair](http://www.gknaerospace.com/fan-blade-repair)