

CFM56-5B 1ST STAGE FAN DISK

Reference

Engine Service Manual 72-21-03

Typical Part Numbers

338-001-503-0, 338-001-504-0

General Information

Solid Titanium Design,

1 Fan Disk per Engine, 2 Engines per Aircraft

Aircraft Type : AIRBUS A319, A320, A321

1150 West Bradley, El Cajon, CA 92020

Phone: (619) 258-5109

E-mail: Repairs@USA.GKNAerospace.com

Visit us at: www.gkn.com/fan-blade-repair

Available Repair Scope

Basic Overhaul:

Inspection 001	Clean, Crack Detect, Eddy Current Inspect and Detail Inspection
Repair 002	Replace Crimped Self-Locking Nuts
Repair 006	Shot peening of Disk Dovetails Slots (if applicable)
Repair 016	Replace Crimped Spacers

Additional Repairs:

Repair 012	Blend Repair Surface Damage
Repair 013	Plasma Repair surface "N"
Repair 019	Repair of Wear on the Aft Post

