



# IAE V2500 STAGE 1 FAN DISC

## Reference

Engine Manual 72-31-12

## Typical Part Numbers

5A0269, 5A0337

## General Information

Aircraft Type: A319, A320-200, A321-100/-200, MD90-10/-30/-40

## Available Repair Scope

Engine Manual Inspection/Check 02

- |            |   |
|------------|---|
| Repair 001 | VRS1152 Repairing of Surface Damage                 |
| Repair 005 | VRS1155 Repairing of Curvic Teeth                   |
| Repair 007 | VRS1157 Replacement of Shank Nuts                   |
| Repair 008 | VRS1159 Replacement of Plate Washer                 |
| Repair 009 | VRS1164 Replacement of Rear Ramp                    |
| Repair 010 | VRS1158 Replacement of Locating and Jacking Pad Pin |
| Repair 011 | VRS1154 Replacement of Dry Film Lubricant           |

GKN Aerospace Repair Solutions West  
1150 West Bradley Avenue  
El Cajon, CA 92020  
Visit us at: [www.gknaerospace.com/fan-blade-repair](http://www.gknaerospace.com/fan-blade-repair)