



# CFM56-5B 1st STAGE FAN DISK

## Reference

Engine Service Manual 72-21-03

## Typical Part Numbers

338-001-503-0, 338-001-504-0

## General Information

Solid Titanium Design, 1 Fan Disk per Engine, 2 Engines per Aircraft  
Aircraft Type : AIRBUS A319, A320, A321

## Available Repair Scope

### Basic Overhaul:

Inspection 001 Clean, Crack Detect, Eddy Current Inspect and Detail Inspection

Repair 002 Replace Crimped Self-Locking Nuts

Repair 006 Shot peening of Disk Dovetails Slots (if applicable)

Repair 016 Replace Crimped Spacers

### Additional Repairs:

Repair 012 Blend Repair Surface Damage

Repair 013 Plasma Repair surface "N"

Repair 019 Repair of Wear on the Aft Post

SB 72-1101 Repair of Wear on the Aft Post

GKN Aerospace Repair Solutions West  
1150 West Bradley Avenue  
El Cajon, CA 92020  
Visit us at: [www.gknaerospace.com/fan-blade-repair](http://www.gknaerospace.com/fan-blade-repair)